

Certificate

Admission to implementation
of Volkswagen test regulations



by

Volkswagen AG
Materials technology

for

Altran CZ a.s.
Příčná 2071
508 01 Hořice
Czech Republic

The laboratory service provider **Altran CZ a.s.** has successfully compared the test procedures listed in the Appendix at the above-mentioned locations or at the aforementioned sub-suppliers with Volkswagen.

This certificate entitles the laboratory service provider to offer the tests listed in the Appendix worldwide as a certified laboratory service provider of Volkswagen in accordance with the regulations, the declaration of conformity he has issued, from **01.04.2021 to 31.03.2022.**

Wolfsburg, 14.04.2021

i. V. Dr. Christian Achmus
Head of Materials Technology Brand VW

i.V. Petr Sobotka
Laboratory manager Brand Skoda

List of test procedures that can be offered to Volkswagen suppliers

Blatt 1 von 1

Service provider: **Altran CZ a.s.**

Region: **Europa**

Location or subcontracting in the attached location legend



Zertifiziert von
Volkswagen

	Label	Description of test procedures	Note	Location
1	TL 1010	Materials for Vehicle Interiors; Burning Behavior; Material Requirements		A
2	PV 3987	Scrub Resistance (Micro-Scratch Resistance) of High- Gloss Surfaces in the Vehicle Interior		A

Location legend:

Service provider: **Altran CZ a.s.**

Region: **Europa**

Nr.	Company name	Street	Place	Country
A	Altran CZ a.s.	Příčná 2071	508 01 Hořice	Czech Republic