

# Certificate

Admission to implementation  
of Volkswagen test regulations



by

**Volkswagen AG**  
**Materials technology**

for

**Altran CZ a.s.**  
**Příčná 2071**  
**508 01 Hořice**  
**Czech Republic**

The laboratory service provider **Altran CZ a.s.** has successfully compared the test procedures listed in the Appendix at the above-mentioned locations or at the aforementioned sub-suppliers with Volkswagen.

This certificate entitles the laboratory service provider to offer the tests listed in the Appendix worldwide as a certified laboratory service provider of Volkswagen in accordance with the regulations, the declaration of conformity he has issued, from **01.04.2021 to 31.03.2024.**

Wolfsburg, 14.04.2021

---

i. V. Dr. Christian Achmus  
Head of Materials Technology Brand VW

---

i.V. Petr Sobotka  
Laboratory manager Brand Skoda

List of test procedures that can be offered to Volkswagen suppliers

Blatt 1 von 1

Service provider: **Altran CZ a.s.**

Region: **Europa**

Location or subcontracting in the attached location legend



Zertifiziert von  
Volkswagen

Label	Description of test procedures	Note	Location
1	<b>PV 1200</b>	Vehicle Parts; Testing the Environmental Cycle Resistance (80 °C/-40 °C)	A
2	<b>PV 1210</b>	Body and Add-On Parts/Hang-On Parts; Corrosion Test	A
3	<b>PV 1306</b>	Non-Metallic Materials; Exposure Test for Determining the Tackiness of Polypropylene Parts	A
4	<b>PV 2005</b>	Vehicle Parts; Testing of Resistance to Environmental Cycle Test	A
5	<b>PV 3905</b>	Organic Materials; Ball Drop Test	A
6	<b>PV 3929</b>	Non-Metallic Materials; Weathering in Dry, Hot Climate (Exterior)	A
7	<b>PV 3930</b>	Non-Metallic Materials; Weathering in Humid, Hot Climate (Exterior)	A
8	<b>PV 3952</b>	Plastic Components for the Vehicle Interior; Scratch Resistance Test	A
9	<b>PV 3964</b>	Surfaces in the Passenger Compartment; Testing of Cream Resistance	A
10	<b>PV 3966</b>	PP Components; Stress Whitening Properties (Ball Drop Test)	A
11	<b>PV 3974</b>	Plastic Components; Determination of the Mar Resistance of Surfaces without Finish Treatment in Vehicle Interiors And Exteriors	A

<b>12</b>	<b>PV 3989</b>	Plastics for Components in the Exterior Area; Ball Drop Test	A
<b>13</b>	<b>PV 3.3.3</b>	Paints and Varnishes; Scratch Resistance Testing of Clear Coats	A

### Location legend:

Service provider: **Altran CZ a.s.**

Region: **Europa**

<b>Nr.</b>	<b>Company name</b>	<b>Street</b>	<b>Place</b>	<b>Country</b>
A	Altran CZ a.s.	Příčná 2071	508 01 Hořice	Czech Republic